

Just like a size 10 shoe in one brand can be a size 9 ½ in another, all tires don't come as a standard size either. Ordering FMTV wheel assembly, NSN 2530-01-500-4619, can bring two different tires. So make sure you take a good look at the manufacturer and the tread. The Goodyear tire is about an inch taller than the Michelin option.



Finally, make sure your spare tire matches the tires on your truck. The spare needs to at least match one of the axles. As a general rule for all Army vehicles, make sure the spare tire matches the tires that are already installed.

## M1117 ASV Seat Switch NSN

If the electric switch for the hydraulic seat on your M1117 armored security vehicle (ASV) goes bad, don't replace it with NSN 6150-01-577-4987 (Item 1 in Fig 69A of TM 9-2320-307-24P). That brings the switch and bracket at a cost of almost \$1,650! Instead, reuse the old bracket and replace just the switch with NSN 5930-00-765-5719. That sets you back only \$51.88.

PS 725 11 APR 13